




The pipes are small and there is little head pressure and no gradient along the bottom of the caravan. The drains are naturally slow to drain. This might be the best that you can do. Call us 0220 694828 if you have further concerns.